
From: Jerry K Miles (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=KEVI49201A]
Sent: 3/14/2016 7:34:41 AM
To: Jeffrey R Marcell (Generation - 3) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Jeff136]
Subject: RE: Problem with Flow able fill in S107 needs to be resolved

The engineer specified no more than a 12 inch slump in the specs and they sent 8 inch. The 8 inch wouldn't flow so we had a call late Friday and the engineer specified minimum of 12 this time. I still don't like it and Rueben and I had a better idea but we got out voted. If they doesn't work maybe they will go with our idea next. I hope this works though.

From: Jeffrey R Marcell (Generation - 3)
Sent: Monday, March 14, 2016 7:32 AM
To: Jerry K Miles (Generation - 34)
Cc: Jeffrey C Heffelman (Generation - 3)
Subject: RE: Problem with Flow able fill in S107 needs to be resolved

What was the solution?

Jeff Marcell

Environmental Supervisor

Possum Point Power Station

Ladysmith & Remington CT Sites

703-441-3813 (phone)

8-795-3813 (tie)

703-441-3897 (fax)

From: Jerry K Miles (Generation - 34)
Sent: Monday, March 14, 2016 7:31 AM
To: Jeffrey C Heffelman (Generation - 3)
Cc: Jeffrey R Marcell (Generation - 3)
Subject: RE: Problem with Flow able fill in S107 needs to be resolved

We have another path forward on this and will begin pouring again Tuesday. If All goes well we will Pour again Thursday and it will be complete.

From: Jeffrey C Heffelman (Generation - 3)
Sent: Friday, March 11, 2016 6:32 PM
To: Jerry K Miles (Generation - 34)
Subject: Re: Problem with Flow able fill in S107 needs to be resolved

Thanks

Sent from my iPhone

On Mar 11, 2016, at 3:41 PM, Jerry K Miles (Generation - 34) <Jerry.K.Miles@dom.com> wrote:

Gentlemen.

This is an update for you guys. We had a problem with the flow able fill not flowing through the pipe properly. I have called all stop to the work until we get it resolved and sent the email below to the design parties. They have already responded and are looking at solutions. I will keep you update.

Thanks

Kevin

From: Jerry K Miles (Generation - 34)
Sent: Friday, March 11, 2016 3:14 PM
To: 'Scott Quinlan'; 'John Klamut'; Michael A Glagola (Generation - 34); Carter Cole (Generation - 34); David R Payne (Generation - 34)
Cc: Christine Harris (Generation - 34); Reuben Williams
Subject: Problem with Flow able fill in S107 needs to be resolved
Importance: High

Gentlemen,

The flow able fill in S107 Toe Drain is not flowing properly. It is a piling up within 12 feet or so of the entrance and not flowing. I believe there is not enough grade on the pipe for it to flow all the way to the other end. I have called and all stop to the work until we resolve this. In my opinion the only solution is to do as follows. Somehow reinforce the North Bulk Head to handle any back pressure with a steel plate of some strength and add a fitting into the top of it. Drill a vent hole in the top of the pipe on the south end behind the bulkhead, then pump from the north end until the concrete comes up to the top of the vent hole in the South end. In my opinion that is the only way to safely be sure it is full. Please remember I have called a stop to this work and we need to resolve this as soon as possible.

Sincerely,

J. Kevin Miles

Project Manager-Possum Point

Fly Ash Removal

803-983-3344